

ENVIRO-SAFE

REFRIGERANTS

Directions for use

Follow all safety precautions to use this product! Read and understand all instructions and warnings first!

1. Connect the torch head to the gas cylinder outdoors in a well ventilated area.
2. Check torch to make sure there is no leaking.
3. If it is leaking, you will smell a rotten egg or sulfur smell.
4. If a leak is detected, make sure the torch is fully seated on the can of fuel.
Do NOT overtighten!
5. If the can is tight to the torch and there is still a leak, disconnect the torch from the fuel cylinder and DO NOT USE THE TORCH and call us immediately at 888-913-1110.
6. After the torch is checked and no leaks are detected, you may take it to the job site.
7. Make sure the area is clear of any flammable, combustible, or explosive material.
8. This torch may be used to solder copper pipes as it comes from the box.
9. If you are going to solder electric wires or electrical components, remove solder tip from the plastic box and push it onto the torch head.
10. If you are using the heat shrink tip, remove the solder tip and replace it with the heat shrink tip. Caution: The tip will be HOT after use, let it cool before touching.
11. The torch also becomes very hot after use.
12. The torch reaches a temperature of 2100°F.
13. The torch is not intended for continuous burning. Shut off after the soldering job is completed.
14. Torch tips are located inside the heat shrink tubing box.
15. To use the heat shrink, find the proper size for your wire.
16. Install on the electric wire before soldering joint.
17. Solder joint.
18. Slide heat shrink over exposed solder joint.
19. Install heat shrink tip on torch head.
20. Adjust flame on the torch.

21. Get close to heat shrink and you will see heat shrink sticking to the wire.
22. Watch that you do not get too close to heat shrink as it is possible to melt it.
23. For best results, always use Boss Torch gas available on our website. Item #5435
24. One can of fuel will burn about 20 hours at low flame.

Additional cans of fuel may be purchased at: <http://www.es-refrigerants.com/products/w/id/62/t/boss-torch-gas-refill/details.asp>

Safety Instructions for use of Torch, Heat Shrink,

Installing Solder & Heat Tip

1. Read all instructions FIRST!
2. Use common sense and follow all safety precautions.
3. Always wear safety glasses/goggles and any personal protective equipment deemed necessary to protect yourself before use.
4. Be always watchful and only use in areas with plenty of fresh air.
5. Never use this torch near flammable, combustible or explosive contents.
6. Connect torch to fuel cylinder outdoors.
7. NEVER change fuel cylinder indoors.
8. Before lighting the torch make sure torch is securely tightened and there is no leaking of fuel.
9. If there is leaking of fuel, you will get a rotten egg smell – much like sulfur.
10. If there is leaking, DO NOT USE!

